

Huawei.H12-421.v2022-03-31.q79

Exam Code:	H12-421
Exam Name:	HCIP-Data Center Facility Deployment V1.0
Certification Provider:	Huawei
Free Question Number:	79
Version:	v2022-03-31
# of views:	1784
# of Questions views:	790
https://www.freegas.com/qa/Huawei/H12-421/Huawei.H12-421.v2022-03-31.q79.html	

NEW QUESTION: 1

How many NetCol5000-C water-cooled line-class precision air conditioners can be supported by one NetCol520 chilled water distribution unit?

- A. 6
- B. 8
- C. 12
- D. 10

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 2

The EPO status interface of the UPS5000-E can select a normally open or normally closed interface according to actual use.

- A. True
- B. False

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 3

NetCol5000-A air conditioner compressor exhaust temperature is too high, what are the reasons? (Multiple Choice)

- A. The refrigerant circuit or device is clogged
- B. Too little refrigerant charge
- C. The outdoor unit is not installed correctly.
- D. condenser filth blockage leads to poor heat dissipation

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 4

NetEco does not support sending reports to customers by email.

- A. True
- B. False

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 5

When a fire occurs in the cabinet, what is used to activate the gas fire extinguishing device on site?

- A. Fire cylinders
- B. Pressure switch
- C. Solenoid valve
- D. Emergency stop button / manual deflation button

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 6

When the temperature detector or smoke detector in the FusionModule1000 generates an alarm, () emits a continuous beeping sound to remind you to take measures as soon as possible to avoid a major accident. (Multiple choice)

- A. Temperature detector
- B. Smoke detector
- C. Buzzer
- D. Sound and light alarm

Answer: B,C,D ([LEAVE A REPLY](#))

NEW QUESTION: 7

When the UPS2000-G-(6-20kVA) is in ECO mode, the battery indicator and bypass indicator are on at the same time.

- A. False
- B. True

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 8

In NetEco "Video" function, you can enter () and other operations (Multiple choice)

- A. Create a camera
- B. Video live browsing
- C. Delete the camera
- D. Modify the camera

Answer: A,B,C,D ([LEAVE A REPLY](#))

NEW QUESTION: 9

The rated capacity of the battery: also called the nominal capacity, according to the national standard or line standard requirements, is the lowest capacity value that should be released.

- A. TRUE
- B. FALSE

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 10

When the internal short circuit of the battery occurs, the faulty battery charging voltage (), the open circuit voltage is low (generally less than 1V/cell).

- A. all possible
- B. High
- C. No change
- D. Low

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 11

The ECC800 supports two AC inputs.

- A. FALSE
- B. TRUE

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 12

You cannot search for an alarm by setting a filter condition on NetEco's Current Alarms page.

- A. False
- B. True

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 13

In the "Video" function of NetEco, you can perform operations such as (). (Multiple Choice)

- A. Create a camera
- B. Modify the camera
- C. Video live browsing
- D. Delete the camera

Answer: A,B,C,D ([LEAVE A REPLY](#))

NEW QUESTION: 14

When the FusionModule1000 fire protection system is adjusted, the smoke detector can be heated to simulate the fire alarm of the temperature sensor.

- A. TRUE

B. FALSE

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 15

Which of the following is not the reason why the NetCol 8000-A infrared humidifier water tray is not filled with water?

- A.** Inlet line valve is not open
- B.** The water pressure is abnormal
- C.** The water injection pipe is blocked
- D.** Infrared lamp damage

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 16

Three sets of 9Ah battery packs are connected in parallel and connected to UPS2000-G-6kVA. What is the battery capacity set?

- A.** 27Ah
- B.** 9Ah
- C.** 18Ah
- D.** 32Ah

Answer: A ([LEAVE A REPLY](#))

Valid H12-421 Dumps shared by PrepPdf.com for Helping Passing H12-421 Exam! PrepPdf.com now offer the **newest H12-421 exam dumps**, the PrepPdf.com H12-421 exam **questions have been updated** and **answers have been corrected** get the **newest** PrepPdf.com H12-421 dumps with Test Engine here:
<https://www.preppdf.com/Huawei/H12-421-prepaway-exam-dumps.html> (240 Q&As Dumps, **40%OFF** Special Discount: **Exam-Tests**)

NEW QUESTION: 17

Which of the following air conditioning systems need to be equipped with a cooling tower or dry cooler?

- A.** DX air-cooled type
- B.** Direct ventilation air conditioning system
- C.** DX water-cooled type
- D.** CW air-cooled type

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 18

In () setting interface, you can set the linkage rule of the multi-function sensor and the sunroof.

- A. Access control user management
- B. WiFi management
- C. Version information
- D. PLC

Answer: [\(SHOW ANSWER\)](#)

NEW QUESTION: 19

UPS2000-A-(1-3kVA) closes the mains input switch and directly enters the bypass working state.

- A. TRUE
- B. FALSE

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 20

The RH2288 server supports () power input.

- A. 1
- B. 4
- C. 3
- D. 2

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 21

The user can modify the ECC800's IP address from the () menu of the ECC800 Web interface.

- A. Video IP settings
- B. Time setting
- C. Monitoring module IP
- D. Emblem module settings

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 22

At present, the industry PUE value can be optimally achieved ().

- A. 0.5
- B. 2
- C. -0.5
- D. 1.06

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 23

To modify the plane view of the ECC800 micromodule, need to log in to the Web to operate with administrator privileges.

A. False

B. True

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 24

Users can monitor the status of devices such as UPS and air conditioner on the ECC800.

A. TRUE

B. FALSE

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 25

Which of the following supports the UPS5000-E-400K-FM input line voltage? (Multiple choice)

A. 400V

B. 380V

C. 415V

D. 220V

Answer: A,B,C ([LEAVE A REPLY](#))

NEW QUESTION: 26

FusionModule1000 is an indoor intelligent micro-module data center solution.

A. True

B. False

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 27

Among the components of the UPS5000-E, () can be hot plug. (Multiple choice)

A. Energy Control Sheet

B. Bypass module

C. Dry joint card

D. Power module

Answer: A,B,C,D ([LEAVE A REPLY](#))

NEW QUESTION: 28

When installing the Huawei air-cooled air conditioner, the refrigerant pipeline positive pressure is required to be () hours.

A. 8

B. 12

C. 24

D. 36

Answer: (SHOW ANSWER)

NEW QUESTION: 29

DOD (depth of discharge) indicates the percentage of battery discharge and battery rated capacity.

A. True

B. False

Answer: A (LEAVE A REPLY)

NEW QUESTION: 30

Through the ECC800Web interface, what can users do? (Multiple choice)

A. Software upgrade

B. Query version information

C. Export historical data

D. Real-time monitoring of device status

Answer: A,B,C,D (LEAVE A REPLY)

NEW QUESTION: 31

When a fire occurs in the cabinet and the fire extinguishing device releases the extinguishing agent into the protection zone, what will display the words "Don't let in".

A. Sound and light alarm

B. Fire alarm bell

C. Venting indicator

D. Emergency light

Answer: C (LEAVE A REPLY)

Valid H12-421 Dumps shared by PrepPdf.com for Helping Passing H12-421 Exam!

PrepPdf.com now offer the **newest H12-421 exam dumps**, the PrepPdf.com H12-421 exam **questions have been updated** and **answers have been corrected** get the **newest** PrepPdf.com H12-421 dumps with Test Engine here:

<https://www.preppdf.com/Huawei/H12-421-prepaway-exam-dumps.html> (240 Q&As

Dumps, **40%OFF** Special Discount: **Exam-Tests**)

NEW QUESTION: 32

The following statement about the integration UP5000-E-120K-HASBS, which is wrong?

A. Support smart battery management, adjustable battery sections

B. Support the incoming line

C. The energy statistics interface can display the energy of each output branch

D. ATS does not support manual switching

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 33

The refrigerant air cylinder of Huawei air-cooled air conditioner does not need to be inverted on the electronic scale when charging the refrigerant.

A. True

B. False

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 34

Huawei Fusion Module2000 monitoring system supports users on which to monitor the status of micro-modules? (Multiple choice)

A. ECC 800Web interface

B. Mobile APP

C. NetEco web interface

D. PAD APP

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 35

What does the gas fire extinguishing system startup principle include? (Multiple choice)

A. Manual start

B. Emergency start

C. Automatic start

D. Safe start

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 36

The data center energy efficiency PUE is as small as possible, and the minimum can be close to zero.

A. False

B. True

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 37

The communication option card of UPS2000G only has Modbus card and SNMP card.

A. TRUE

B. FALSE

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 38

When the integrated UPS is wired, if the input phase sequence is wrong, the machine will not work.

A. True

B. False

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 39

In the case of normal mains, the UPS battery in inverter mode may be executed ().

(Multiple choice)

A. Shallow discharge test

B. Checking the capacity test

C. Float charging

D. Balanced charging

Answer: A,B,C,D ([LEAVE A REPLY](#))

NEW QUESTION: 40

In the process of using the battery, in order to reduce the deterioration of the voltage imbalance between the batteries, it is necessary to increase the charging voltage of the battery pack, and to activate and charge the battery to extend the battery life, which is called ().

A. Charging test

B. Self-discharge

C. Balanced charging

D. Floating charge

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 41

The following air conditioning systems need to be equipped with a cooling tower or dry cooler ().

A. DX air-cooled type

B. DX water-cooled type

C. Direct ventilation air conditioning system

D. CW air-cooled type

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 42

For storage batteries that have been stored for 18 months or longer, the battery that has not been recharged should be processed ().

A. Need to supplement the electricity treatment, use as soon as possible

B. Disposal

C. No need to deal with, use as soon as possible

D. Need activation treatment, use as soon as possible

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 43

The power indicator of the gas fire extinguishing controller is on and the alarm indicator is off indicating that the gas fire extinguishing controller is working properly.

A. False

B. True

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 44

During the use of the battery pack, the appearance is normal, but there is no current during charging, and the voltage drop is zero at the moment of discharge, and it cannot be discharged. What could be happened in the following?

A. Sulfation

B. Breaking the battery pack

C. Battery leakage

D. backward battery

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 45

The Netcol 5000-A35kW uses an electronic expansion valve.

A. True

B. False

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 46

The NetCol5000-A35kW indoor unit installation needs to be connected to the zero line.

A. True

B. False

Answer: B ([LEAVE A REPLY](#))

Valid H12-421 Dumps shared by PrepPdf.com for Helping Passing H12-421 Exam! PrepPdf.com now offer the **newest H12-421 exam dumps**, the PrepPdf.com H12-421 exam **questions have been updated** and **answers have been corrected** get the **newest** PrepPdf.com H12-421 dumps with Test Engine here:
<https://www.preppdf.com/Huawei/H12-421-prepaway-exam-dumps.html> (240 Q&As Dumps, **40%OFF** Special Discount: **Exam-Tests**)

NEW QUESTION: 47

After the air conditioner is commissioned, the indoor temperature is in a reasonable state, and the suction pressure is not lower than ().

- A. 5MPa
- B. 0.7MPa
- C. 6Mpa
- D. 7MPa

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 48

The NetCol5000-A air conditioning humidification function may be invalid because of ().
(Multiple choice)

- A. Humidifier circuit breaker is not closed
- B. The outdoor unit is not running
- C. Low indoor temperature
- D. Humidification barrel is damaged

Answer: A,B,D ([LEAVE A REPLY](#))

NEW QUESTION: 49

In the FusionModule1000, all the fire-fighting cables of the open line are worn with metal hoses, and the pipe ends are protected by a wire sleeve to prevent damage to the fire-fighting cables when a fire occurs.

- A. False
- B. True

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 50

In general, the air supply distance of the air duct is shorter than that of the hood air supply.

- A. TRUE
- B. FALSE

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 51

UPS2000-G-(6-20kVA) battery is not connected and does not affect the normal power supply of the system, but the UPS loses the backup power supply capability.

- A. True
- B. False

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 52

The same group of batteries cannot be mixed with batteries of different capacities, different specifications, different batches, and different manufacturers.

A. TRUE

B. FALSE

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 53

You can view the camera's name, code, IP address, model, status, and more in NetEco's Video menu.

A. False

B. True

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 54

Where is the recommended installation location for the Smart ETH socket?

A. Side of the cable trough on the top of the cabinet

B. Inside the threshold

C. Inside the network cabinet

D. Control skylight

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 55

The camera coding can be obtained by ().

A. IVS client

B. WiFi converter

C. Smart ETH socket

D. ECC800

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 56

Before the battery is installed, a single battery open circuit voltage is required: 12V battery is greater than or equal to 12.60V or 2V battery is greater than or equal to 2.10V. When it is found to be unqualified, the battery needs to be recharged.

A. False

B. True

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 57

Which of the following options is a natural cooling system?

A. Water-cooled cold water air conditioning system

B. Water-cooled cold air conditioning system

- C. Direct ventilation air conditioning system
- D. Air-cooled direct expansion air conditioning system

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 58

When four UPS2000G-20K parallel units are set and the number of redundant units in the parallel setting is set to "1", the capacity of the system is () KVA.

- A. 60
- B. 80
- C. 100
- D. 40

Answer: ([SHOW ANSWER](#)**)**

NEW QUESTION: 59

The UPS2000-G-(6-20kVA) did not report a fault but the load was cut off due to a poor connection of the output cable.

- A. True
- B. False

Answer: ([SHOW ANSWER](#)**)**

NEW QUESTION: 60

When the UPS5000-E shares the battery pack, the battery capacity parameter of each UPS is set to the total capacity of the entire battery pack.

- A. False
- B. True

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 61

In the installation scenario where the indoor unit is higher than the outdoor unit, the oil trap must be set.

- A. False
- B. True

Answer: A ([LEAVE A REPLY](#))

Valid H12-421 Dumps shared by PrepPdf.com for Helping Passing H12-421 Exam! PrepPdf.com now offer the **newest H12-421 exam dumps**, the PrepPdf.com H12-421 exam **questions have been updated** and **answers have been corrected** get the **newest** PrepPdf.com H12-421 dumps with Test Engine here:

NEW QUESTION: 62

The video can be viewed on NetEco only after the video camera is configured on the IVS.

- A. True
- B. False

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 63

The dry contact signal of the UPS5000-E does not support the remote emergency stop function.

- A. True
- B. False

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 64

If the status of the access which collected by the network management is always open, it can be checked by (). (Multiple choice)

- A. Check if the access control actuator and the door magnetic lock wiring are normal.
- B. Check if the suction plate angle and tightness on the door are suitable
- C. Check AC actuator wiring
- D. Check if the door of access monitoring is closed

Answer: ([SHOW ANSWER](#)**)**

NEW QUESTION: 65

By setting the mailbox parameters, the NetEco system will send an email to notify the user according to the set rules.

- A. True
- B. False

Answer: ([SHOW ANSWER](#)**)**

NEW QUESTION: 66

When inspecting, maintaining and repairing electrical equipment in non-blackout mode, a warning sign or signage should be placed on the electrical installation and work area.

- A. True
- B. False

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 67

The principle of the () humidifier is that the high-intensity infrared lamp causes the water surface to release water vapor and diffuse into the air stream that needs to be humidified.

- A. High pressure fogging
- B. Infrared
- C. Wet film
- D. Electrode

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 68

When the device interface uses the Modbus-RTU protocol, what needs to be installed when accessing the ECC800?

- A. ETH converter
- B. sunroof actuator
- C. AC actuator
- D. Access control actuator

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 69

The device accesses the ECC800 monitoring system through a smart ETH socket, using the () interface of the intelligent FTH socket.

- A. PoE
- B. AI/DI
- C. FE
- D. RS485

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 70

The assembly unit that can realize RS485/CAN to FE interface conversion is ().

- A. Sunroof actuator
- B. Smart ETH socket
- C. ETH converter
- D. WiFi converter

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 71

When there are multiple computer rooms and are monitored at the same time, it is possible to generate a hierarchical deployment of the monitoring system.

- A. TRUE
- B. FALSE

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 72

When calculating the battery capacity, the battery discharge capacity coefficients of the different backup times are the same.

A. False

B. True

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 73

The Fusion Module2000 is an outdoor prefabricated integrated data center solution.

A. False

B. True

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 74

The UPS5000-E accepts input voltage frequency in a range of () Hz.

A. 45-70

B. 40-70

C. 50-60

D. 55-65

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 75

When installing the UPS battery, the installation tool does not need to be insulated because the load is not charged.

A. False

B. True

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 76

What may NetCol 5000-C insulation cotton damage result in?

A. The drainage capacity of the equipment is significantly reduced

B. Fan blocked

C. Fan noise is too loud

D. Pipeline condensation

Answer: D ([LEAVE A REPLY](#))

Valid H12-421 Dumps shared by PrepPdf.com for Helping Passing H12-421 Exam!
PrepPdf.com now offer the **newest H12-421 exam dumps**, the PrepPdf.com H12-421 exam **questions have been updated** and **answers have been corrected** get the

newest PrepPdf.com H12-421 dumps with Test Engine here:

<https://www.preppdf.com/Huawei/H12-421-prepaway-exam-dumps.html> (240 Q&As

Dumps, **40%OFF** Special Discount: **Exam-Tests**)

NEW QUESTION: 77

Which of the following is not part of the NetCol 5000-C30kW precision air conditioner.

- A. EC fan
- B. PID flow regulating valve
- C. DC fan high efficiency power supply module
- D. DC inverter compressor

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 78

Deploying on demand and avoiding over-investment is the only advantage of a modular data center.

- A. False
- B. True

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 79

When a fire occurs in the FusionModule1000 box, the deflation indicator will show the words "Don't put in" to warn the site personnel not to enter the deflation zone.

- A. False
- B. True

Answer: B ([LEAVE A REPLY](#))

Valid H12-421 Dumps shared by PrepPdf.com for Helping Passing H12-421 Exam!

PrepPdf.com now offer the **newest H12-421 exam dumps**, the PrepPdf.com H12-421 exam **questions have been updated** and **answers have been corrected** get the **newest** PrepPdf.com H12-421 dumps with Test Engine here:

<https://www.preppdf.com/Huawei/H12-421-prepaway-exam-dumps.html> (240 Q&As

Dumps, **40%OFF** Special Discount: **Exam-Tests**)